

Subtotal (1)

\$2,169.00

Estimated Shipping

\$0.00

Total

\$2,169.00

Details

3591
 Quote number # 3000178206813
 Created June 17, 2024
 Expires July 17, 2024
 Created by
 quotes@salud.unm.edu

Billing

Tax exemption
 I am not tax exempt

Shipping

Payment method

Items

Quantity

Unit Price

Item total



Precision 3591-High End Config

1

\$4,613.00

\$4,613.00

Discounted unit price: \$2,169.00
 Contract Code: C000001111525
Estimated Ship Date
 June 28, 2024 - July 2, 2024

Catalog Number: 84 / rrcrc966232-7943998

| Category | Description | Code | SKU | ID |
|--------------------|--|---------|------------|------|
| Base | Dell Mobile Precision Workstation 3591 | GQRFS1Y | [210-BLNG] | 1 |
| Processor | Intel® Core™ Ultra 7 165H, vPro® Enterprise (24MB, 16 cores, 22 threads, up to 5.0 GHz Turbo, 45W) | GLD03G1 | [379-BFQW] | 146 |
| Operating System | Windows 11 Pro, English, Brazilian Portuguese, French, Spanish | G01OVWE | [619-ARSB] | 11 |
| Microsoft Office | Activate Your Microsoft 365 For A 30 Day Trial | GC7OFJV | [658-BCSB] | 1002 |
| Chassis Options | Intel Core Ultra 7 165H Processor with vPro and NVIDIA RTX 1000 Ada 6GB GDDR6 | G5URGY0 | [329-BKFB] | 149 |
| Graphics | NVIDIA RTX 1000 Ada Generation, 6 GB GDDR6 | G36NS4P | [490-BKCD] | 6 |
| Display | 15.6" FHD 1920x1080, 60Hz, 250 nits, Non-Touch, FHD HDR RGB Camera, Mic, WLAN | GTIK94H | [391-BJCS] | 760 |
| Camera | FHD HDR RGB Camera, TNR, Camera Shutter, Microphone | GKZIM8N | [319-BBKK] | 379 |
| Memory | 32 GB: 2 x 16 GB, DDR5, 5600 MT/s, non-ECC | G0ILPCW | [370-BBYH] | 3 |
| Storage | 1TB, M.2 2280, Gen4 PCIe NVMe, SSD, Class 40 | GTF29KC | [400-BRHX] | 8 |
| Additional Storage | No Additional Hard Drive | GBAK075 | [401-AAGM] | 637 |
| Raid Connectivity | NO RAID | GX5Q06T | [817-BBBN] | 1009 |
| Keyboard | English US backlit AI hotkey keyboard with numeric keypad, 99-key | GK5OBMC | [583-BLNH] | 4 |
| PalmRest | Single Pointing, No Security | GMU7PKE | [346-BKTQ] | 55 |
| Wireless | Intel AX211, 2x2 MIMO, 2400 Mbps, 2.4/5/6 GHz, Wi-Fi 6/6E (Wi-Fi 802.11ax), Bluetooth | GZ35794 | [555-BKND] | 19 |
| Mobile Broadband | No Mobile Broadband Card | GR9571Y | [556-BBCD] | 114 |

| Category | Description | Code | SKU | ID |
|------------------------------------|---|---------|-----------------------|-------------|
| Primary Battery | 6 Cell, 97 Wh | GR0JCSG | [451-BDDL] [451-BDDJ] | 112 |
| Power Supply | 130W Type-C Power Adapter | GLSA1V7 | [492-BDGH] | 1015 |
| Systems Management | Intel vPro Management Disabled | GV3CYXI | [631-BBXF] | 49 |
| ENERGY STAR | ENERGY STAR Qualified | G6J34SM | [387-BBLW] | 122 |
| EPEAT 2018 | EPEAT 2018 Registered (Gold) | GBU8CHM | [379-BDZB] | 200331 |
| Windows AutoPilot | No AutoPilot | GYE02AP | [340-CKSZ] | 291 |
| Power Cord | E5 Power Cord 1M for US | G39AK0Z | [537-BBDK] | 20 |
| Documentation | Safety and Regulatory Documents English, French, Dutch | GDJVQ4P | [340-AGIK] | 21 |
| Mouse | No Mouse | G8043UZ | [570-AADK] | 12 |
| Wireless Driver | Intel AX211 WLAN Driver | G0J75D9 | [555-BKSB] | 7 |
| EAN/UPC Labels | No UPC Label | GY0A2B8 | [389-BCGW] | 292 |
| Shipping Material | Packaging for 130W Adapter | G073VC6 | [340-DQNC] | 465 |
| FGA Module | No FGA | NOFGA | [817-BBBB] | 572 |
| Processor Label | Intel Core Ultra 7 Non-vPro Label | G9QI5ME | [340-DMQL] | 749 |
| Non-Microsoft Application Software | Dell Additional Software | GCUA4G1 | [658-BFPP] | 1003 |
| Placemat | Quick Setup Guide for Mobile Precision 3591 | GRUDBZ3 | [340-DQRD] | 60 |
| ICPS | No ICPS | GJ5LQFG | [650-BBBG] | 141 |
| Protect your new PC | No anti-virus software | GD4K19S | [650-AAAM] | 1014 |
| Operating System Recovery Options | OS-Windows Media Not Included | GLA90Q1 | [620-AALW] | 200013 |
| Service | 4Y Basic Onsite Service after remote diagnosis with Hardware-Only Support | NBD4 | [997-1079] [997-1129] | 29 |
| Intel Responsiveness Technologies | Intel® Rapid Storage Technology Driver | GUKQ7JP | [409-BCXX] | 707 |
| Transportation from ODM to region | BTO Standard Shipment | G2GRFNL | [800-BBGS] | 200080 |
| Premier discount | | | | -\$2,444.00 |

Item total: \$2,169.00

Savings: \$2,444.00

Subtotal (1): \$2,169.00

Savings \$2,444.00

Subtotal (1) \$2,169.00

Estimated Shipping \$0.00

Total \$2,169.00

[Account](#) Account
Your Profile

Dell Contacts

[Your Products](#) Your Products
Quotes

Sales Quotes

Systems

Anti-Slavery & Human Trafficking

Ultrabook, Celeron, Celeron Inside, Core Inside, Intel, Intel Logo, Intel Atom, Intel Atom Inside, Intel Core, Intel Inside, Intel Inside Logo, Intel vPro, Itanium, Itanium Inside, Pentium, Pentium Inside, vPro Inside, Xeon, Xeon Phi, Xeon Inside, and Intel Optane are trademarks of Intel Corporation or its subsidiaries in the U.S. and/or other countries.

Same day shipment subject to order size limitations, Dell standard shipping methods and payment via credit card, gift card or Dell Business Credit.[^] Notification will be provided if there are payment delays which could impact shipping date. Electronics and accessories may ship separately.

Smart Selection. Limited quantities. Only available for orders placed by 5:59 p.m. CT Mon.–Thurs. Systems shipped the next business day after an order is placed. Subject to order approval. Software and accessories not part of the configuration will be shipped separately and may arrive after your system. Please note that Smart Selection Configuration pricing cannot be combined with other pricing offers or discounts provided or agreed to by Dell. Orders with Custom Factory Integration might require additional processing time.

Onsite Service After Remote Diagnosis and Other Important Information: *On-site Service or Advanced Exchange Service after remote diagnosis: (a) On-site Service after remote diagnosis is determined by the online or phone technician, and may involve customer access to the inside of the system and multiple extended sessions. If the issue is covered by the Limited Hardware Warranty and cannot be resolved remotely, the technician and/or replacement part will be dispatched, usually in 1 or 2 business days, following the completion of the remote diagnosis. The customer must return the original hardware to Dell according to the rules specified. On-site service is provided by Dell Marketing L.P.; Availability varies. Other conditions apply. (b) Advanced Exchange Service replaces hardware after remote diagnosis. The customer must return the original hardware to Dell according to the rules specified. Advanced Exchange Service is subject to country availability. (c) For complete details about On-site Service or Advanced Exchange Service, see dell.com/servicecontracts

[^]DELL BUSINESS CREDIT (DBC): Offered to business customers by WebBank, who determines qualifications for and terms of credit. Taxes, shipping and other charges are extra and vary. The Total Minimum Payment Due is the greater of either \$20 or 3% of the New Balance shown on the statement rounded up to the next dollar, plus all past due amounts. Dell and the Dell logo are trademarks of Dell Inc.

****Payment solutions provided and serviced by Dell Financial Services L.L.C. or its affiliate or designee ("DFS") for qualified customers.** Offers may not be available or may vary in certain countries. Where available offers may be changed without notice and are subject to product availability, applicable law, credit approval, documentation provided by and acceptable to DFS and may be subject to minimum transaction size. Offers not available for personal, family or household use. Dell Technologies and the Dell Technologies logo are trademarks of Dell Inc. Restrictions and additional requirements may apply to transactions with governmental or public entities.

¹Subject to applicable law and regulations. ALL ORDERS ARE SUBJECT TO APPROVAL AND ACCEPTANCE BY DELL. Pricing, availability and other terms of offer may be withdrawn or changed without notice. Dell cannot be held responsible for errors in typography or photography. ALL ORDERS ARE SUBJECT TO APPROVAL AND ACCEPTANCE BY DELL. Pricing, availability and other terms of offer may be withdrawn or changed without notice. Dell cannot be held responsible for errors in typography or photography.