

Savings

Total

Subtotal (1)

Estimated Shipping

\$808.00

\$1,073.00

\$808.00 \$0.00

Item total

\$1,881.00

Details

Billing

Shipping

1


Payment method

\$1,881.00

HSC Standard Precision 3460 Quote number # 3000177918884

Created June 14, 2024 Expires July 14, 2024 Created by quotes@salud.unm.edu Tax exemption I am not tax exempt

Items	Quantity	Unit Price



Discounted unit price: \$808.00 Contract Code: C000001111525

Estimated Ship Date

June 21, 2024 - June 24, 2024

Catalog Number: 94 / ror ~066222<u>-</u>7042842

Category	Description	Code	SKU	ID
Base	Precision 3460 SFF CTO BASE	GB125MG	[210-BCTU]	1
Operating System	Windows 11 Pro, English, French, Spanis h	G0Y1P9E	[619-AQLP]	11
Processor	Intel® Core™ i5 14500 (24 MB cache, 14 cores, 20 threads, up to 5.0 GHz Turbo, 6 5 W)	GMBH6QV	[338-CPNY] [412- AAZQ]	146
Systems Management	Intel Management Engine disabled	GFRYQL5	[631-ADHI]	49
Intel Performance Features	Intel® Rapid Storage Technology Driver, Precision 3460	GT7Y86C	[409-BCWM]	707
Memory	16 GB: 2 x 8 GB, DDR5, 5600MT/s, SO-DI MM, non-ECC	G4501UZ	[370-BBXM]	3
Graphics	Intel Integrated Graphics	GUJTPY1	[490-BBBS]	6
Storage Configuration (Boot Drive)	C1 SSD Boot + SSD	GPQ8B5W	[449-BBYR]	276
HDD Controller	Integrated Intel Sata Control	G5LRCFD	[403-BBCE]	9
Storage	256 GB, M.2, PCle NVMe, SSD, Class 35	G9CPWFD	[400-BNBY] [412- AAZZ]	8
2nd Storage	No Hard Drive	GMKB05E	[400-AKZR]	637
3rd Storage	No Hard Drive	GMKB05E	[400-AKZR]	54
4th Storage	No Hard Drive	GMKB05E	[400-AKZR]	51
5th Storage	No Hard Drive	GMKB05E	[400-AKZR]	52
CD ROM/DVD ROM	No Optical Drive	GZEN0K3	[429-ABKR]	16
Optical Software	PowerDVD Software not included	GI5LS2C	[632-BBBJ]	597
Raid Connectivity	No SATA RAID	G9BYT4Q	[780-BBCJ]	1009
Chassis Options	Precision 3460 SFF with 300W (80 Plus P latinum) PSU, RPL-R compatible	GBUCDZ9	[321-BKYG]	116
Additional Storage Devices - Media Reader	No SD Card Reader	G86J5QK	[385-BBBL]	10
Network Card	No Additional Network Card Selected (Integrated NIC included)	GPQ31WV	[555-BBJ0]	13

Category	Description	Code	SKU	ID
	·			
PCIe I/O Cards	Not selected in this configuration	GY2RECF	[817-BBBC]	666
Wireless	No Wireless LAN Card (no WiFi enableme nt)	GE7Y41P	[555-BBFO]	19
Keyboard	Dell Multimedia Wired Keyboard - KB216 Black - US English	GZDPBC1	[580-ADJC]	4
Mouse	Dell Optical Mouse - MS116 (Black)	GWDQT30	[570-ABIE]	12
Microsoft Office	Activate Your Microsoft 365 For A 30 Day Trial	GC70FJV	[658-BCSB]	1002
ENERGY STAR	ENERGY STAR Qualified	G6J34SM	[387-BBLW]	122
EPEAT	EPEAT 2018 Registered (Gold)	GBU8CHM	[379-BDZB]	200331
TPM Security	Dell Precision TPM	G1MEH6P	[340-ACBY]	297
Driver	No Wireless LAN	GW1SM6D	[555-BBNI]	7
Documentation/Disks	Safety/Environment and Regulatory Guid e (English/French Multi-language)	G7RB0GY	[340-AGIK]	21
Placemat	Quick Setup Guide, Precision 3460	GQF6JID	[340-CYUT]	60
UPC Label	No UPC Label	GCB 2EM	[389-BDCE]	292
Packaging	Shipping and Handling Single-Pack	G2GC6KM	[340-CQYR] [340- CBUU]	465
Label	Precision 3460 Plat Reg Label DAO	GZ8HME6	[389-ECXZ]	676
Processor Branding	Intel® Core™ i5 Processor Label	G2HQMXF	[340-CUEW]	749
Internal Speakers	Internal Speaker	GR068XC	[520-AARD]	18
Stands and Mounts	No Stand	GK0645E	[575-BBCH]	558
Video Card Cable	No Additional Cable	GIX0L8M	[379-BBCY]	592
External Speakers	No External Speaker	GTNM7E2	[817-BBBC]	200095
Non-Microsoft Application Software	Additional Software	GT2ECRJ	[658-BFRV]	1003
Power Cord	System Power Cord C13 (US 125V, 15A)	GPYN5HX	[450-AHDU]	20
Operating System Recovery Options	OS Windows Media Not Included	GZK9Y5J	[620-AALW]	200013
Windows AutoPilot	No AutoPilot	GYE02AP	[340-CKSZ]	291
FGA Module	No FGA	NOFGA	[817-BBBB]	572
Services:Hardware Support	4Y Basic Onsite Service after remote dia gnosis with Hardware-Only Support	NBD4	[997-2812] [997- 2808]	29
Optional Integrated Video or USB Ports	No Additional Port	GH2ILWN	[492-BCLP]	36
Security Software and PC Protection	No anti-virus software	GD4K19S	[650-AAAM]	1014
Premier discount				-\$1,073.00

Item total: \$808.00

Savings: \$1,073.00

Subtotal (1): \$808.00

Savings \$1,073.00

Subtotal (1) \$808.00

\$0.00

Estimated Shipping

Total \$808.00

Account Account Your Profile

Dell Contacts

Your Products Your Products

Quotes

Sales Quotes

Systems

Peripherals

Legal & Regulatory Terms of Sale Privacy Statement Do Not Sell or Share My Personal Information Accessibility

Anti-Slavery & Human Trafficking

Ultrabook, Celeron, Celeron Inside, Core Inside, Intel, Intel, Intel, Intel Logo, Intel Atom, Intel Atom Inside, Intel Core, Intel Inside, Intel Inside Logo, Intel VPro, Itanium, Itanium Inside, Pentium, Pentium Inside, vPro Inside, Xeon, Xeon Phi, Xeon Inside, and Intel Optane are trademarks of Intel Corporation or its subsidiaries in the U.S. and/or other countries.

Same day shipment subject to order size limitations, Dell standard shipping methods and payment via credit card, gift card or Dell Business Credit. Notification will be provided if there are payment delays which could impact shipping date. Electronics and accessories may ship separately.

Smart Selection. Limited quantities. Only available for orders placed by 5:59 p.m. CT Mon.—Thurs. Systems shipped the next business day after an order is placed. Subject to order approval. Software and accessories not part of the configuration will be shipped separately and may arrive after your system. Please note that Smart Selection Configuration pricing cannot be combined with other pricing offers or discounts provided or agreed to by Dell. Orders with Custom Factory Integration might require additional processing time.

Onsite Service After Remote Diagnosis and Other Important Information: *On-site Service or Advanced Exchange Service after remote diagnosis: (a) On-site Service after remote diagnosis is determined by the online or phone technician, and may involve customer access to the inside of the system and multiple extended sessions. If the issue is covered by the Limited Hardware Warranty and cannot be resolved remotely, the technician and/or replacement part will be dispatched, usually in 1 or 2 business days, following the completion of the remote diagnosis. The customer must return the original hardware to Dell according to the rules specified. On-site service is provided by Dell Marketing L.P; Availability varies. Other conditions apply. (b) Advanced Exchange Service replaces hardware after remote diagnosis. The customer must return the original hardware to Dell according to the rules specified. Advanced Exchange Service is subject to country availability. (c) For complete details about On-site Service or Advanced Exchange Service, see dell.com/servicecontracts

^DELL BUSINESS CREDIT (DBC): Offered to business customers by WebBank, who determines qualifications for and terms of credit. Taxes, shipping and other charges are extra and vary. The Total Minimum Payment Due is the greater of either \$20 or 3% of the New Balance shown on the statement rounded up to the next dollar, plus all past due amounts. Dell and the Dell logo are trademarks of Dell Inc.

**Payment solutions provided and serviced by Dell Financial Services L.L.C. or its affiliate or designee ("DFS") for qualified customers. Offers may not be available or may vary in certain countries. Where available offers may be changed without notice and are subject to product availability, applicable law, credit approval, documentation provided by and acceptable to DFS and may be subject to minimum transaction size. Offers not available for personal, family or household use. Dell Technologies and the Dell Technologies logo are trademarks of Dell Inc. Restrictions and additional requirements may apply to transactions with governmental or public entities.

'Subject to applicable law and regulations. ALL ORDERS ARE SUBJECT TO APPROVAL AND ACCEPTANCE BY DELL. Pricing, availability and other terms of offer may be withdrawn or changed without notice. Dell cannot be held responsible for errors in typography or photography. ALL ORDERS ARE SUBJECT TO APPROVAL AND ACCEPTANCE BY DELL. Pricing, availability and other terms of offer may be withdrawn or changed without notice. Dell cannot be held responsible for errors in typography or photography.